
Diagnostic Health Report





Quick Check® now has the capability to retrieve potential repair information in the inspection lane to allow your customers to make informed decisions in seconds.



VIN entry required.

Requires subscription to Code Assist from Identifix, separate from Direct Hit.





(Your logo)

Hunter Engineering Co. 11250 Hunter Drive Bridgeton, MO 63044 Tel: 314-731-3020 M-F: 8:15 am - 5:00 pm

Sa: Closed Su: Closed

Alex Nicholas, Service Manager

Honda 2003 Accord LX/LX-P/SE/EX/EX-L






March 22, 2017 10:24 AM

Diagnostic Health Report

Powered by: IDENTIFIED AND FIX PABTER

Diagnostic Trouble Code		Top Reported Repair
■ P0300	Multiple Cylinders Misfiring, or Cannot Identify Cylinder Due to CMP Sensor Failure	Engine Valve(s)
■ P0420	Catalyst Efficiency Below Threshold (Bank 1)	Catalytic Converter(s)
■ P0139	Heated Oxygen Sensor (Bank 1 Sensor 2) Slow Response	Heated Oxygen Sensor (HO2S) Bank 1 Sensor 2 (B1S2)

Most Likely Repair Statistics



Other Reported Repairs

■ P0300: Multiple Cylinders Misfiring, or Cannot Identify Cylinder Due to CMP Sensor Failure

Cylinder Head Gasket(s) Idle Air Control (IAC) Valve w/P0302, P0303 Ignition Coil Pack(s) w/P0302, P0303 Ignition Coil(s)

P0420: Catalyst Efficiency Below Threshold (Bank 1)

Air Fuel (A/F) Ratio Sensor Catalytic Converter Burn-Off Procedure Downstream Oxygen (O2) Sensor Engine Control Module (ECM) Engine Control Module (ECM) Programming Heated Oxygen Sensor (HO2S) Bank 1 Sensor 2 (B1S2) Oxygen (O2) Sensor(s) Emission Monitor Drive Cycle(s)

Exhaust Pipe

■ P0139: Heated Oxygen Sensor (Bank 1 Sensor 2) Slow Response

Downstream Oxygen (O2) Sensor
Engine Control Module (ECM) Programming
Heated Oxygen Sensor (HO2S) Bank 1 Sensor 2
(B1S2) Wiring
Oxygen (O2) Sensor(s)
Rear Oxygen (O2) Sensor
Rear Oxygen (O2) Sensor Wiring
Air Fuel (A/F) Ratio Sensor
Bank 1 Air/Fuel (A/F) Ratio Sensor

Engine Conrol Module (ECM) Programming