

(Your logo)

Hunter Engineering Company 11250 Hunter Drive Bridgeton, MO 63044


Tel: (314) 731-3020

Mon-Fri: 8:15 am - 5:00 pm

Sat: Closed Sun: Closed

Alex Nicholas, Service Manager

Complimentary Vehicle Inspection



April 3, 2017 | 10:43 AM **Lexus : IS 350 F Sport : 2016**

Last in Date: 12/30/16 2:17 PM



MO AC6Z8S



Wheel Alignment















Recommend comprehensive alignment check for added tire life, fuel economy and safety.





Tire Health

FAILED









Tread depth values are in 32nds of an inch.



(Your logo)

Hunter Engineering Company 11250 Hunter Drive Bridgeton, MO 63044 Tel: (314) 731-3020

Mon-Fri: 8:15 am - 5:00 pm

Sat: Closed Sun: Closed

Alex Nicholas, Service Manager

Complimentary Vehicle Inspection



April 7, 2017 | 3:37 PM

Chevrolet: Malibu with Electric Power Steering: 2012

Last in Date: 1/8/17 11:54 AM





11,752 M





Wheel Alignment

FAILED











Recommend comprehensive alignment check for added tire life, fuel economy and safety.




Stopping Check







Diagnostic Check














Check Engine Light - OFF



0 Trouble Codes are present



Recommend a brake inspection






No additional service needed




Tire Health


PASSED





TEST







Tread depth values are in 32nds of an inch.



State of Health

Measured: 387 CCA Voltage: 12.3 V

OEM Ref.: 585 CCA

